

Checklist

ool

CLEARING DEBRIS: START BY REMOVING ANY DEBRIS

pening

REMOVE COVER: CAREFULLY TAKE OFF THE POOL COVER

INSPECT ALL POOL EQUIPMENT

FILL THE POOL WITH WATER TO THE APPROPRIATE LEVEL

SCRUB THE WALLS AND FLOORS OF THE POOL TO REMOVE ANY ALGAE OR RESIDUE

TEST THE CHEMICAL BALANCE OF THE WATER

APPLY SHOCK TREATMENT TO THE POOL TO ELIMINATE ANY BACTERIA OR ALGAE

RUN THE FILTER

THOROUGHLY INSPECT ALL SAFETY EQUIPMENT

CONDUCT A DETAILED FINAL INSPECTION